



- 3 Watt. Continuous Rotation
- 50 Ohm Wirewound Potentiometer
- Includes Mounting Hardware



HX41-50

50 Ohm Wirewound Potentiometer. 3 Watt. Includes Mounting Hardware

50 Ohm Wirewound Potentiometer, 3 Watt. Continuous Rotation. 3 / 8 " Bushing Length; 3 / 8 " Long Flatted Shaft. Includes Mounting Hardware